





G12

 3,5x25 x10


E38

 x2


P15

 x5


A1

 ø7x50 x8


W1


 x2


G4

 4x16 x16


B7

 ø8x30 x40

N13

 M4x22 x2

G2

 3x20 x40


W2

 x1

D3

 PZ35PR x2

C3

 Z350D x2

F1


 x4

H7

 400mm x2


G10

 6x13 x8




I



II



III



IV

