



G12  
3,5x25 x10



P15  
x5



S1  
416mm x1



S2  
x5



W1  
x4




N13  
M4x22 x8



D3  
PZ35PR x4



H7  
x4




E38  
x8




G4  
4x16 x32



G2  
3x20 x60




C3  
Z35PR x4



350mm x4


A1  
ø7x50 x14



B7  
ø8x30 x70



W2  
x1




F1  
x4




G10  
6x13 x16




I




II




III



IV



V



VI

