







G12  
  
 3,5x25 x8


E38  
  
 x2


P15  
  
 x4


A1  
  
 ø7x50 x16


W1  
  
 x2


G4  
  
 4x16 x10


B7  
  
 ø8x30 x44

N13  
  
 M4x22 x2

G2  
  
 3x20 x40

W2  
  
 x1

D3  
  
 PZ35PR x2


C3  
  
 Z350D x2

F1  
  
 x4


H7  
  
 350mm x1

G10  
  
 6x13 x4



II



II



III



IV

